

Spain Government

| Serial Number | Version | Manufacturers Serial Number | Fate |
|---------------|-------------------------------------|-----------------------------|------------------|
| EC-CDE | E.20 {Beechcraft 95-B55 Baron} | TC-1554 | |
| EC-CDE | E.20 {Beechcraft 95-B55 Baron} | TC-1555 | |
| EC-CDG | E.20 {Beechcraft 95-B55 Baron} | TC-1578 | |
| EC-CDH | E.20 {Beechcraft 95-B55 Baron} | TC-1582 | |
| EC-CDI | E.22 {Beechcraft 65-C90 King Air} | LJ-603 | |
| EC-CDJ | E.22 {Beechcraft 65-C90 King Air} | LJ-605 | |
| EC-CDK | E.22 {Beechcraft 65-C90 King Air} | LJ-608 | |
| EC-CHA | E.22 {Beechcraft 65-C90 King Air} | LJ-621 | |
| EC-CHB | E.22 {Beechcraft 65-C90 King Air} | LJ-623 | Written Off 1980 |
| EC-CHC | E.22 {Beechcraft 65-C90 King Air} | LJ-624 | |
| EC-CLG | E.24B {Beechcraft 35-F33A Debonair} | CE-520 | |
| EC-CLH | E.24B {Beechcraft 35-F33A Debonair} | CE-521 | |
| EC-CLI | E.24B {Beechcraft 35-F33A Debonair} | CE-525 | |
| EC-CLJ | E.24B {Beechcraft 35-F33A Debonair} | CE-529 | |
| EC-CLK | E.24B {Beechcraft 35-F33A Debonair} | CE-530 | |
| EC-CLL | E.24B {Beechcraft 35-F33A Debonair} | CE-531 | |
| EC-CLM | E.24B {Beechcraft 35-F33A Debonair} | CE-532 | |
| EC-CLN | E.24B {Beechcraft 35-F33A Debonair} | CE-537 | |
| EC-CLO | E.24B {Beechcraft 35-F33A Debonair} | CE-542 | |
| EC-CLP | E.24B {Beechcraft 35-F33A Debonair} | CE-544 | |
| EC-CLQ | E.24B {Beechcraft 35-F33A Debonair} | CE-547 | |
| EC-CLR | E.24B {Beechcraft 35-F33A Debonair} | CE-574 | |
| EC-COA | E.20 {Beechcraft 95-B55 Baron} | TC-1808 | |
| EC-COB | E.20 {Beechcraft 95-B55 Baron} | TC-1811 | |
| EC-COC | E.20 {Beechcraft 95-B55 Baron} | TC-1814 | |
| EC-COD | E.20 {Beechcraft 95-B55 Baron} | TC-1834 | |
| EC-COE | E.20 {Beechcraft 95-B55 Baron} | TC-1838 | |
| EC-COF | E.20 {Beechcraft 95-B55 Baron} | TC-1844 | |
| EC-COG | E.20 {Beechcraft 95-B55 Baron} | TC-1850 | |
| EC-COH | E.20 {Beechcraft 95-B55 Baron} | TC-1853 | |
| EC-COI | E.22 {Beechcraft 65-C90 King Air} | LJ-663 | |
| EC-COJ | E.22 {Beechcraft 65-C90 King Air} | LJ-664 | |
| EC-COK | E.22 {Beechcraft 65-C90 King Air} | LJ-665 | |
| EC-COL | E.22 {Beechcraft 65-C90 King Air} | LJ-666 | |
| EC-COM | E.24B {Beechcraft 35-F33A Debonair} | CE-576 | |
| EC-CON | E.24B {Beechcraft 35-F33A Debonair} | CE-579 | |
| EC-COO | E.24B {Beechcraft 35-F33A Debonair} | CE-583 | |
| EC-COP | E.24B {Beechcraft 35-F33A Debonair} | CE-584 | |
| EC-COQ | E.24B {Beechcraft 35-F33A Debonair} | CE-585 | |
| EC-COR | E.24B {Beechcraft 35-F33A Debonair} | CE-588 | |
| EC-COS | E.24B {Beechcraft 35-F33A Debonair} | CE-590 | |
| EC-COT | E.24B {Beechcraft 35-F33A Debonair} | CE-593 | |
| EC-COU | E.24B {Beechcraft 35-F33A Debonair} | CE-586 | |
| EC-COV | E.24B {Beechcraft 35-F33A Debonair} | CE-587 | |
| EC-COX | E.24B {Beechcraft 35-F33A Debonair} | CE-589 | |
| EC-COY | E.24B {Beechcraft 35-F33A Debonair} | CE-517 | |
| EC-GBB | Beechcraft 200 Super King Air | BB-182 | |

